

ZyClear™

Clear Gloss Coating

Wheel Application Guide

ZyCoat's ZyClear "on wheels," is a revolutionary coating designed to enhance the durability and performance of automotive wheels. Below, you will find detailed information regarding the application process and the benefits of using ZyClear to protect and preserve your wheels from brake dust pitting, UV degradation, and environmental damage. ZyClear provides an easy to clean and maintain finish.

Here is a short video illustrating the process:

<https://youtu.be/Vzm3QBQkmas?si=0iQ8tIOPPf99IBM9>



Review ZyClear and ZyClean Safety Data Sheet prior to use.

Materials Needed (included in Part # 15505)

- ZyClear #15005 coating
- ZyClear #15100 Lint Free cloths—two per kit
- ZyClean #15108 (for surface preparation/cleaning)
- ZyCoat #15509 Rubber Gloves

Application Process

1. Surface Preparation:

- Clean the wheels thoroughly ZyClean (Part #15108) using ZyClear Lint Free cloths (Part #15100) to remove any dirt, grease, or contaminants. Allow 10-15 minutes for ZyClean to flash off.
- Ensure the surface is dry and free from any residue.



2. **IMPORTANT**

Masking: Mask off areas where Wheel Weights are often installed. DO NOT APPLY ZYCLEAR TO THESE MASKED OFF AREAS!!



continued...

...continued

3. Application:

- Wipe on ZyClear evenly onto the surface of the wheel using a ZyClear “lint free” cloth, or spray with 0.8 tip.
- Allow the coating to cure for the recommended time, typically 60 minutes.
- Apply in thin film 6-10 microns thick.

4. Additional Coat or Touch Up ZyClear:

- If desired, apply an additional coat of ZyClear for added protection, a more glossy finish, or to touch up.
- Follow the same application process above, allowing each coat to quickly flash off and apply 2nd coat within 5 minutes of applying the 1st coat. Apply 2 coats for optimal coverage.



5. Curing:

- For optimal results, allow the coated wheels to air cure for 60 minutes in an area out of direct sunlight with moderate temperature (<85°F) and relatively moderate humidity.
- Avoid exposure to moisture or contaminants during the curing process.

Maintenance:

- After curing, maintain the coated wheels by regularly washing with a pH-neutral car wash soap and water.
- Avoid using abrasive cleaners or harsh chemicals that may degrade the coating.
- Reapply as necessary following same application process detailed above.

Benefits of ZyClear on Wheels

Superior Protection

ZyClear forms a durable barrier on the surface of the wheels, providing protection against corrosion, brake dust, UV discoloration, oxidation, and environmental damage.

Enhanced Appearance

The clear coating enhances the appearance of automotive wheels, giving them a glossy, showroom finish that lasts.

Easy Maintenance

With ZyClear, cleaning & maintaining the appearance of coated wheels is simple, requiring minimal effort and time.

Long-Lasting Performance

ZyClear is engineered to withstand the rigors of daily driving, ensuring long-lasting performance and protection for automotive wheels. Applying ZyClear to your wheels will exceed your expectations and provide unparalleled protection and enhancement. One two ounce bottle of ZyClear will treat a set of four wheels. Should you have any further questions or require additional information, please do not hesitate to contact us.